

Product Discontinuity Notice

ISP130301 BM BL PDN v1.0

Device affected	Package code		
ISP130301-BM	All versions		
ISP130301-BL			

Date (YYYY-MM-DD)	PDN reference	Document version
2021-04-01	ISP130301_PDN	1.0

Reason for discontinuity

Several components and materials required for module manufacturing are discontinued.

Last order date	Last shipping date
-----------------	--------------------

2021-10-01 2022-04-01

Alternative solution for customer

Re-design the application with newer module generation which are smaller and compliant for power supply, IOs, integrated antenna design rules and firmware.

Approvals

Quality Director: Date: Signature:

Chris Barratt 2021-04-01

Operation Manager: Date: Signature:

Philippe Genin 2021-04-01